# **Notice**

Model:



Effective from : Chassis No. P42840-07

CORRECTION	■ PRODUCTION CHANGE	
SERVICE FLASH	ADD INFORMATION	FILE NO.
Please add this no	ted below. REVISION 0	
Category: COLO	R TELEVISION	Date: _AUGUST / 30 / 2010

Destination: U.S.A. / CANADA REF : No. SM780171-07

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P42840-00. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P42840-00 used in Model DP42840 (SM780171).

## SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

### 1. IN THE SERVICE ADJUSTMENTS

**DP42840** 

#### PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be changed from 08h to 09h in the table and in Note 2.

## 2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

Page &

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Sect		Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 19, Chassis Electrical Parts List	A100	Old	1AA0B10N28100	ASSY,PWB,MAIN_B-N7AL	1	NO	D	
		New	1AA0B10N281A0	ASSY,PWB,MAIN_B-N7AM	1	NO		
Page 9, Chassis Electrical Parts List	C1807	Old	CK0J106KGMBNG	CERAMIC 10U Z 6.3V	1	NO	. D	
		New	N/A	NOT USED	0	NO		
	C1811 .	Old	N/A	NOT USED	0	NO	- D	
		New	CK1H103KLZBNG	CERAMIC 0.01U K 50V	1	NO		
	C1820	Old	N/A	NOT USED	0	NO	D	
		New	CK1A105KLZBNG	CERAMIC 1U K 10V	1	NO		

© Sanyo Manufacturing Corporation 2010

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 9, Chassis Electrical Parts List	D1800	Old	N/A	NOT USED	0	NO	D
		New	DD1SS352G	DIODE 1SS355-TE-17	1	NO	
Page 19, Chassis Electrical Parts List	<b>▲</b> EL901	Old	1AV4T40C18400	LCD(T420HW06 V2,S02,S11)	1	NO	D
		New	1AV4T40C05500	LCD(LC420WUN-SBA1)	1	NO	
Page 14 Chassis Electrical Parts List	R841	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R842	Old	N/A	NOT USED	0	NO	D
	11042	New	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W	1	NO	D
	R1831	Old	N/A	NOT USED	0	NO	, D
	N 1031	New	1LB4L26B0700G	INDUCTOR, 120 OHM	1	NO	
	D1025	Old	RGF1002JTCANL	MT-GLAZE 10K JA 1/10W	1	NO	D
	R1835	New	N/A	NOT USED	0	NO	
Page 16 Chassis	R1839	Old	N/A	NOT USED	0	NO	D
Electrical Parts List		New	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W	1	NO	
	R1842	Old	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W	1	NO	D
		New	RGF2201JTCANL	MT-GLAZE 2.2K JA 1/10W	1	NO	
	R1855	Old	N/A	NOT USED	0	NO	D
		New	RGF1000JTCANL	MT-GLAZE 100 JA 1/10W	1	NO	
	R6312	Old	N/A	NOT USED	0	NO	D
Page 17, Chassis Electrical Parts List		New	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	
	R6314	Old	N/A	NOT USED	0	NO	D
		New	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	
	R6319	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R6321	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R6322	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
Page 19, Chassis	<b>≜</b> WK5LV -PN	Old	1AA4W30B62700	CORD42INCH,40P-51P(LVDS)	1	NO	D
Electrical Parts List		New	1AA4W30B62600	CORD42INCH,40P-51P(LVDS)	1	NO	

© Sanyo Manufacturing Corporation 2010

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

August 2010 SMC

Published in Mexico